

LCD Panel Repair

ANNOUNCEMENT



Lexmark Operator Panel PN 99A0001



November 1, 2005

Hong Video Technology, Inc. (HVT), the leader in flat panel display repair, today announces repair service for the Lexmark™ Operator Panel, part number 99A0001. The part is used in Lexmark Optra S Series, Optra SC1275, and Optra Color 1200 printers.

Repair services reduce cost by 50% or more compared to replacement when the Lexmark Operator Panel becomes defective. The repair price starts at \$40.00 per unit. Volume discounts are available.

Turnaround time for repair service is typically fewer than ten days. HVT guarantees all repaired units will meet manufacturer specification and warrants all repairs for six months.

Common defects of the Lexmark Operator Panel 99A0001 are missing lines and bleeding. Having conducted a thorough engineering analysis of the Lexmark Operator Panel, HVT is prepared to repair these defects immediately upon receipt of the defective parts.

For more information about Lexmark Operator Panel repair services or other display product services, please contact Hong Video Technology at 770-495-4881 or visit www.fpddepot.com.

About HVT

Hong Video Technology, Inc. (HVT) is a leader in the display service industry, helping customers reduce total cost of ownership of display products by providing high-quality repair services. Since starting business in 1994, HVT has earned a solid reputation for engineering excellence, business integrity, and unmatched customer service.

Lexmark is a trademark of Lexmark International, Inc.

© Copyright 2005 by Hong Video Technology, Inc.



Hong Video Technology, Inc.

Servicing Display Products Since 1994

3150 Clinton Court | Norcross, GA 30071 | Tel: 770-495-4881 | www.fpddepot.com